

PRIORITY

25X1
25X1

25X1

25X1

THE LENS IN THE FOWARD CAMERA PRODUCED THE HIGHEST PRE-FLIGHT AND INFLIGHT RESOLUTION OF ANY CORONA CAMERA SYSTEM TO DATE. THE AVERAGE READINGS OF THE BEST 51/51 CORN TARGETS WERE

WHICH EQUATES TO BETTER THAN 200 CYCLES PER MM AT 88 NM. B. PI SUITABILITY. REPORTED THE PI SUITABILITY FOR THIS MISSION RANGES FROM GOOD TO POOR WITH THE LARGEST PORTION FALLING IN THE FAIR TO POOR CATEGORY. THE CHINA COVERAGE FOR THIS MISSION WAS VERY PRODUCTIVE WITH SEVERAL NEWLY LOCATED UNIDENTIFIED INSTALLATIONS; HOWEVER, WEATHER CONDITIONS AND VEHICLE PROBLEMS RESULTED IN A NON-STANDARD OPERATIONAL MISSION. SEE PARA 6.

25X1
25X1

4. PAN CAMERA ANOMALIES:

A. PROBLEM-A SMALL FOREIGN DEPOSIT IN FRAME 4, PASS A09E, AFT CAMERA, CAUSED A BASE SCRATCH THROUGH PASS D40.

CAUSE-THE SCRATCH ASSOCIATED WITH THE DEPOSIT OCCURRED DURING PROCESSING.

ACTION-NONE ASSIGNED. WILL GIVE CONTINUED ATTENTION TO CLEANLINESS DURING PROCESSING.

25X1

B. PROBLEM-THE HORIZON FORMAT LOCATIONS OF BOTH FWD AND AFT UNITS ARE SLIGHTLY ERRATIC WITH RESPECT TO THE MAIN CAMERA FORMATS. THE TWO FORMATS NEVER OVERLAP; HOWEVER, A MINIMUM DISTANCE OF .06 INCH INTERMITTENTLY OCCURS BETWEEN THE HORIZON AND THE ADJACENT PAN FRAME.

CAUSE-THE MINIMUM DISTANCE OCCURS ONLY ON THE SHUTDOWN FRAME. THE VARIANCE OR SLIGHTLY ERRATIC DISTANCES ARE CONSIDERED NORMAL FOR THIS TYPE OF TRANSPORT SYSTEM. THE INSTRUMENT TIMING APPEARS TO BE SET SUCH THAT DURING THE CREEP FRAME TRANSPORT OCCURS A BRIEF INSTANT BEFORE PHOTOGRAPHY IS COMPLETE. THIS CAUSES A SLIGHTLY LONGER FORMAT LENGTH RESULTING IN A SHORTER DISTANCE BETWEEN THE HORIZON FORMAT AND MAIN CAMERA FORMAT.

ACTION-NO FURTHER ACTION REQUIRED.

C. PROBLEM-MINOR BASE SCRATCH BEGINS IN FRAME 5 OF PASS A09E OF THE FWD LOOKING CAMERA AND CONTINUES THRU THE MIDDLE OF PASS D24. THE SCRATCH WAVES SLIGHTLY BUT IS GENERALLY LOCATED .75 INCH FROM THE BINARY EDGE.

CAUSE-VERY MINOR EFFECT ON MATERIAL. CHARACTERISTICS OF THE SCRATCH MAKE IT IMPOSSIBLE TO DETERMINE CAUSE.

ACTION-NONE REQUIRED.

D. CHARACTERISTIC ANOMALIES HAVING A MINOR EFFECT ON PERFORMANCE.

(1) ROLLER/EQUIPMENT SHADOWGRAPHS ARE PRESENT ON THE FIRST AND LAST PARTS OF MANY PASSES. THESE RANGE FROM .5 TO 1.5 INCHES IN LENGTH ACROSS THE FILM WEB.

(2) SOME PASSES CONTAIN A SMALL ONE-EIGHT INCH WIDE DENSITY FOG PATTERN ACROSS THE FILM WEB. THIS OCCURS ON THE SEVENTH FROM LAST FRAME ON PASSES SO AFFECTED (AFT).

(3) DENDRITIC STATIC IS PRESENT FROM PASS 151 THRU REST OF THE MSN (AFT).

(4) FRAMES 108 AND 109 OF PASS D104 CONTAIN VERY FINE SCRATCHES AND ABRASIONS APPARENTLY ASSOCIATED WITH CUT AND WRAP SEQUENCE.

(5) THE FWD PREFLIGHT MATERIAL AND THE FIRST TEN PASSES CONTAIN TWO ROWS OF PLUS DENSITY STATIC SPOTS OCCURRING AT A FREQUENCY OF 1.6 INCHES, AND ARE LOCATED 1.5 AND .6 INCHES FROM THE TIME TRACK EDGE. THE SPOTS ARE OFFSET

1

1

-3--

ALONG THE FILM WEB .7 INCH FROM EACH OTHER.

(6) CHARACTERISTIC OUT OF FOCUS AREAS COMMON TO THE SYSTEM WERE NOTED ON THE FWD MATERIAL.

(7) THE FIRST FWD PASS CONTAINS SEQUENTIALLY OVEREXPOSED, UNDEREXPOSED, AND SMEARED CAMERA SERIAL NUMBER IMAGES.

(8) RAIL SCRATCHES ARE HEAVY ON THE FWD PREFLIGHT MATERIAL AND DIMINISH SLIGHTLY AS THE MISSION PROGRESSES.

5. A. DISIC CAMERA PERFORMANCE-LAST RECOVERED FRAME FROM THE INDEX CAMERA IS FRAME 102 OF PASS 233. POINT-TYPE STAR IMAGES ARE RECORDED ON STELLAR CAMERAS WITH 15-25 STARS ON THE PORT AND 10-20 STARS ON THE STARBOARD SIDE. INDEX PHOTOGRAPHIC QUALITY IS GOOD AND EQUAL TO BEST OF SERIES. CORONA AND DENDRITIC STATIC DISCHARGES WERE MINIMAL RESULTING IN THE CLEANEST RECORD TO DATE.

B. ANOMALIES-NONE. CHARACTERISTIC OCCURRENCES LISTED FOR REFERENCE:

(1) PLUS DENSITY SKEW MARKS, OUTSIDE THE ACTIVE FORMAT.

(2) MISSING BINARY TIME WORDS DUE TO TIMING BRUSH STOP POINT VARIATIONS.

(3) EMULSION BUILD-UP ON THE STARBOARD RESEAU PLATE, CAUSING MINUS DENSITY SPOTS.

(4) STATIC ON TRAILING EDGE DUE TO FINAL WRAP-UP
XXXXXX

ON THE FILM SPOOL.

6. SYSTEM ANOMALIES:

A. PAYLOAD-NONE.

B. VEHICLE-

(1) THE GUIDANCE SUBSYSTEM USED EXCESSIVE AMOUNTS OF GAS ON-ORBIT CONTRIBUTING TO A MISSION DURATION OF 15 DAYS VICE THE NOMINAL 19 DAY MISSION. ORIGINALLY THIS PROBLEM POSED A POSSIBLE MISSION LENGTH OF 6 TO 9 DAYS.

(2) THE H-TIMER CEASED TO FUNCTION DURING REV 245. APPROXIMATELY 450 FT OF FILM PER CAMERA WAS UNUSED AS A RESULT OF THIS FAILURE.

7. THE FOLLOWING OPEN PET ACTION ITEMS WERE DISCUSSED AND ARE CONSIDERED CLOSED:

A. AC 1110-3-PLUS DENSITY SPOTS. SPOTS WERE VERY FEW AND MINOR ON MSN 114. THIS ALSO CLOSES AC 1111-1.

B. AC 1112-1-EXPOSURE LOSS HORIZON CAMERA.

C. AC 1112-2-FILM, MISC., POWER DROP.

D. AC 1112-3-FILM LOSS, DISIC TAKE-UP.

COMPLETED ACTION SHEETS WILL BE FORWARDED TO ALL ADDRESSEES.

8. COMMENT-THIS CORONA PET REPORT IS SUBMITTED WITH A MIXTURE OF SADNESS AND PRIDE. SADNESS BECAUSE THIS MAY BE THE LAST CORONA PET REPORT. PRIDE BECAUSE WE ARE PROUD TO HAVE BEEN ASSOCIATED WITH THE MOST SUCCESSFUL SATELLITE PROGRAM IN THE HISTORY OF THE NRP. THE PET MEETINGS STARTED IN JUNE OF 1962 WITH AN EVALUATION OF THE "CAMERA MALFUNCTIONS" ON MISSION 9034A. WE HAVE ENJOYED OUR EXPERIENCE KNOWING THAT WE HAVE AIDED IN THE SUCCESS OF THIS PROGRAM. TO ALL THE ORGANIZATIONS WHO HAVE ASSISTED THIS GROUP, IN PARTICULAR [] WE OFFER OUR SINCERE THANKS. TO THOSE WHO WILL FOLLOW US, WE OFFER OUR BEST WISHES FOR SUCCESS THAT HAS BEEN CHARACTERISTIC OF THE CORONA PROGRAM.

T O P S E C R E T

25X1

--END OF MESSAGE-- GP-1